United States Of America

Bepartment of Transportation - Nederal Abiation Administration

Supplemental Type Certificate

Number SA02477AK

This Certificate issued to

Aero Twin, Inc. 2403 Merrill Field Drive Anchorage, Alaska 99501

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations

Original Groduct - Type Certificate Sumber A00007SE

Make Quest Aircraft Design, LLC

Model Kodiak 100

Description of Type Design Change

Installation of the Aero Twin, Inc. External Oxygen Service Port, Kit No. QX-100 in accordance with Master Data List (MDL) QX-100-MDL, Original Issue, dated November 22, 2016, or later FAA approved revision.

Limitations and Conditions

- 1) The installer must determine whether this design change is compatible with previously approved modifications.
- 2) If the holder agrees to permit another person to use this Certificate to alter the product, the holder shall give the other person written evidence of that permission.
- 3) Installation shall be maintained in accordance with Instructions for Continued Airworthiness (ICA) for Aero Twin, Inc. External Oxygen Service Port Kit No. QX-100 for Quest Kodiak 100 Aircraft, Document Number QX-100-ICA, Revision (--), dated August 22, 2016, or later FAA accepted revision.
- Airplane Flight Manual Supplement (AFMS), Document Number QX-100-AFMS, Original Issue, dated November 22, 2016, or later FAA approved revision, is a required part of this installation.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, reveked or a termination date is otherwise established by the Administrator of the Tederal Aviation Administration.

Date of application: August 31, 2016

Date of issuance November 22, 2016

Date reissued

Date amended

August A. Asay

Manager, Anchorage Aircraft Certification Office

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.